





WAVERAIL NET TIE SYSTEM
(PATENTED)

1. FEED A NET LOOP THROUGH THE WAVERAIL AT A POINT FURTHERST FROM THE RING MOUNTING PLATE.
2. PASS HALF THE LENGTH OF THE PE CORD THROUGH THE NET LOOP.



3. FEED EACH END OF THE PE CORD THROUGH THE INSIDE OF THE WAVERAIL AND BACK OUT AGAIN.
4. TENSION THE NET LOOP AND CORD AS YOU GO.



5. FEED THE REMAINING NET LOOPS WHILE REPEATING THE PRECEDING STEPS.
6. FEED ENDS OF CORD THROUGH EXTRA WAVERAIL AND OUT OF THE WAY. TRIM ENDS OF PE CORD

